





San Jacinto River Waste Pits Superfund Site




San Jacinto River Waste Pits Site

291 Surface & subsurface sediment samples within preliminary site boundary.


 Waste Pits
 Southern Impoundment

 Sediment - ng/kg TEQ_{DF} Dioxin



Cap Improvements

- 2 mo. construction
- \$2.9 MM




Partial Stabilization or Removal

- 53,000 yds³
- 12 to 15 mo. construction
- \$11.2 (Alt. 4) or \$24/\$118 million

Full Removal

- 208,000 yds³
- 16 mo. construction
- \$104/\$636 MM





Constructing the enhanced slope along the South Berm in the Eastern Cell using an excavator (for grading the rock) and skid steer (for transporting rock from the stockpile and placing it)
– 1-21-2014



South Berm in the Eastern Cell after completion of the enhancement work 1-21-2014



Central Berm on the eastern slope, near the north end of the berm, after completion of the enhancement work 1-22-2014